


Quality Alert – Seat Sling for Select ExoFit™ Harnesses

Only Affects select ExoFit™ harnesses manufactured from June 2017 to the end of May 2018

3M Fall Protection has received reports that the aluminum reinforcement plate used in the seat sling on certain DBI-SALA ExoFit™, ExoFit XP™ (inc. Arc Flash), and ExoFit NEX™ (inc. Arc Flash) harnesses can become dislodged from the webbing. In a few instances, the aluminum seat plate has separated from the harness and fallen to the ground, creating a potential dropped object hazard. There have been no reports of injuries or accidents associated with this condition. The performance of the harnesses is unaffected by this issue—they will perform properly in all respects, including as body support for a personal fall arrest system in the event of a fall, even without the added comfort offered by the seat sling.



Representative Seat Sling Indicated by Red Arrow



Manufacture Date on Harness shown in Red Circle

3M is offering a free warranty replacement of the seat sling for all DBI-SALA ExoFit™, ExoFit XP™ (inc. ArcFlash), and ExoFit NEX™ (inc. ArcFlash) harnesses with a seat sling, with a manufacture date of 17/06 (2017, June) through the end of 18/05 (2018, May) regardless of model number.

End-Users: Please inspect your harness, if you find a harness within the affected range with a seat sling, contact 3M Customer Service at 1-800-328-6146 or email us for your free replacement seat sling at 3musfbserviceaction@mmm.com. Please provide us with the model number and manufacture date when contacting us. After you receive your replacement seat sling, please remove your original sling from service and dispose of it.

Distributors: Upon receipt of this notice, please contact our Customer Service department at 800-328-6146 or email at 3musfbserviceaction@mmm.com to obtain a listing of harnesses with seat slings that were sold to you with the affected lot numbers. If you have any of the affected parts in stock, you should return them to 3M Fall Protection for replacements. Please forward this Alert to any of your customers who have purchased affected products from you and provide any assistance requested by your customers to complete the process.

3M remains committed to providing quality products and services to our customers. We apologize for any inconvenience that this situation may cause you. We appreciate your continued support of 3M Fall Protection products and services.


Alerta de calidad: eslinga de asiento para arneses ExoFit™ seleccionados

Solo afecta a unos arneses ExoFit™ seleccionados que se fabricaron entre
junio de 2017 y fines de mayo de 2018

3M Fall Protection ha recibido informes que indican que la placa de refuerzo de aluminio que se usa en la eslinga de asiento puede desprenderse del tejido trenzado en ciertos arneses ExoFit™, ExoFit XP™ (incluyen los modelos para arco eléctrico) y ExoFit NEX™ (incluyen los modelos para arco eléctrico) DBI-SALA. En algunas circunstancias, la placa de asiento de aluminio se ha separado del arnés y se ha caído al suelo, lo que crea el peligro posible de una caída de un objeto. No hemos recibido ningún informe de lesiones o accidentes asociados con esta condición. El desempeño de los arneses no se ve afectado por este problema, por lo que cumplirán correctamente con su propósito en todo momento, hasta como sujeción del cuerpo para un sistema de detención de caídas personal en caso de que se produzca una caída, incluso sin la comodidad adicional que ofrece la eslinga de asiento.



La flecha roja señala la eslinga de asiento del ejemplo



El círculo rojo muestra dónde se encuentra la fecha de fabricación en el arnés

3M ofrece, como parte de la garantía, un reemplazo sin cargo de la eslinga de asiento para todos los arneses ExoFit™, ExoFit XP™ (incluyen los modelos para arco eléctrico) y ExoFit NEX™ (incluyen los modelos para arco eléctrico) DBI-SALA, con una fecha de fabricación entre 17/06 (junio de 2017) y fines de 18/05 (mayo de 2018) independientemente del número de modelo.

Usuarios finales: Inspeccionen el arnés. Si ven que un arnés con eslinga de asiento se encuentra en el grupo de arneses afectados, comuníquense con el Servicio al cliente de 3M llamando al 1-800-328-6146 o envíenos un correo electrónico a 3musfbserviceaction@mmm.com para solicitar el reemplazo sin cargo alguno de la eslinga de asiento. Cuando se comuniquen con nosotros, proporcione el número de modelo y la fecha de fabricación. Una vez que reciba la eslinga de asiento de reemplazo, retire la eslinga original del servicio y descártela.

Distribuidores: Al recibir este aviso, comuníquense con nuestro Servicio al cliente llamando al 800-328-6146 o envíen un correo electrónico a 3musfbserviceaction@mmm.com para obtener una lista de arneses con eslingas de asiento que se les vendieron con los números de lote afectados. Si tienen alguna de las piezas afectadas en existencias, deben devolverla a 3M Fall Protection de inmediato para obtener un reemplazo. Envíen esta Alerta a los clientes que le hayan comprado uno de los productos afectados y bríndenles la asistencia que soliciten para completar el proceso.

3M mantiene su compromiso de ofrecer productos y servicios de calidad a nuestros clientes. Les pedimos disculpas por cualquier inconveniente que esto pueda causarles. Agradecemos su apoyo continuo de los productos y servicios de 3M Fall Protection.